

Lockheed Martin Corporation - Environment, Safety & Health
Burbank Program Office
2550 North Hollywood Way, 3rd Floor Burbank, CA 91505-1055
Facsimile 818-847-0256 or 818-847-0170

137

LOCKHEED MARTIN 

VIA FEDERAL EXPRESS
CAY0599/211 WBS # L2

May 17, 1999

Mr. Peter Chen
Hazardous Substances Engineer
Department of Toxic Substance Control
1011 N. Grandview Avenue
Glendale, California 91201


Dear Mr. Chen:

**Subject: March 1999 Groundwater Monitoring and Offsite Well Installation Report Former,
International Light Metals Facility, Torrance, California
Docket HWCA: P1-98/99-002**

Enclosed please find one copy of the *March 1999 Groundwater Monitoring and Offsite Well Installation Report* prepared by Lockheed Martin Corporation. This report presents the results of Boeing Realty Corporation (Offsite) well installation and groundwater monitoring program for the subject site.

If you have any questions regarding this report, please contact Mr. Masood Choudhury at (818) 847-0512.

Sincerely,


Carol A. Yuge

CAY:MC:gc
Attachment

Mr. Peter Chen

CAY0599/211

May 17, 1999

Page 2

cc w/attachments:

Mr. Jim Ross, RWQCB

Ms. Yolanda Garza, DTSC

Mr. William Rowe, DTSC

Mr. D. Willis, ARCADIS Geraghty & Miller

Mr. Mario Stavale, Boeing Realty Corporation

March 1999 Groundwater Monitoring and Offsite Well Installation Report

Former International Light Metals Facility
19200 S. Western Avenue
Torrance, California



19 May 1999

P R E P A R E D F O R

Lockheed Martin Corp.
Burbank Program Office
2550 Hollywood Way, Suite 305
Burbank, California 91505-1055

March 1999 Groundwater
Monitoring and Offsite Well
Installation Report

Former International Light -
Metals Facility
19200 S. Western Avenue
Torrance, California

Prepared for:
Lockheed Martin Corp.
Burbank Program Office
2550 Hollywood Way, Suite 305
Burbank, California 91505-1055

Prepared by:
ARCADIS Geraghty & Miller, Inc.
1400 Harbor Boulevard, Suite 700
Fullerton, California 92835
Tel 714 278 0992
Fax 714 278 0051

Our Ref.:
CA00280.0004.00003

Date:
19 May 1999


*This document is intended only for the use of
the individual or entity for which it was
prepared and may contain information that is
privileged, confidential, and exempt from
disclosure under applicable law. Any
dissemination, distribution, or copying of this
document is strictly prohibited.*

ARCADIS GERAGHTY & MILLER


**March 1999 Groundwater Monitoring and Offsite Well Installation Report
Former International Light Metals Facility
19200 S. Western Avenue
Torrance, California**

May 19, 1999

Prepared by ARCADIS Geraghty & Miller, Inc.


Teresa A.R. Wilson
Project Manager


Anthony C. Ward, R.G.
Project Officer



This report is executed in one or more counterparts, each of which shall be deemed an original, but all of which either together and separately, constitute one and the same document.

BOE-C6-0007666

1. Introduction	1
1.1 Purpose and Organization	2
1.2 Site Background	3
1.2.1 Geology and Hydrogeology	3
1.2.2 Groundwater Occurrence and Flow	5
1.2.3 Surrounding Area Contamination	6
2. Monitoring Well Installation and Soil Sampling	7
2.1 Methodology	7
2.1.1 Drilling and Soil Sampling	7
2.1.1.1 Permits and Utility Clearance	7
2.1.1.2 Drilling	7
2.1.1.3 Soil Analytical Methodology	8
2.1.1.4 Soil Waste Disposal	8
2.1.2 Monitoring Well Installation	9
2.1.2.1 Well Development	9
2.1.2.2 Water Waste Disposal	10
2.2 Discussion of Monitoring Well Installation and Soil Sampling Results	10
2.2.1 Geological Results	10
2.2.2 Soil Analytical Results	10
2.2.2.1 VOCs	10
2.2.2.2 TPH	11
2.2.2.3 Metals	11
2.2.3 Well Installation Results	11
3. Groundwater Sampling	11
3.1 Methodology	12
3.1.1 General Sampling Methods	12
3.1.1.1 Gauging	12
3.1.1.2 Purging and Sampling	13
3.1.1.3 Sample Handling	13

3.1.1.4	Analytical Methodology	13
3.1.1.5	Quality Control Sampling	14
3.1.1.6	Waste Disposal	15
3.1.2	Off-Site Monitoring Well Methodology	15
3.1.3	Former ILM Facility Methodology	15
3.2	Discussion of Groundwater Monitoring Results	15
3.2.1	Groundwater Elevations	15
3.2.2	Field Results	16
3.2.3	Groundwater Chemical Analyses	17
3.2.3.1	VOCs	17
3.2.3.2	TPH	18
3.2.3.3	Metals	19
4.	QA/QC Evaluation	20
4.1	Objectives of DQOs	20
4.2	Summary of the Data Validation Evaluation	21
5.	References	21

Figures

1. Site Location
2. Surrounding Area
3. Groundwater Monitoring Well Location Map
4. Groundwater Elevations for March 1, 1999
5. TCE in Groundwater - March 1999
6. PCE in Groundwater - March 1999
7. 1,1-DCE in Groundwater - March 1999
8. 1,1-DCA in Groundwater - March 1999
9. TPH-D in Groundwater - March 1999
10. Total Aluminum in Groundwater - March 1999
11. Dissolved Aluminum in Groundwater - March 1999
12. Dissolved Hexavalent Chromium in Groundwater - March 1999

Tables

1. Summary of Soil Analytical Results - Volatile Organic Compounds (VOCs), Total Petroleum Hydrocarbons (TPH), and Metals
2. Groundwater Analytical Sampling Plan
3. Water-Level Elevations, Former ILM Facility
4. Water-Level Elevations, BRC Property
5. Summary of Groundwater Results – Field Water Quality Parameters, Former ILM Facility
6. Summary of Groundwater Results – Field Water Quality Parameters, BRC Property
7. Summary of Groundwater Analytical Results - VOCs, Former ILM Facility
8. Summary of Groundwater Analytical Results - VOCs, BRC Property
9. Summary of Groundwater Analytical Results - TPH, Former ILM Facility
10. Summary of Groundwater Analytical Results - TPH, BRC Property
11. Summary of Groundwater Analytical Results - Dissolved Metals, Former ILM Facility
12. Summary of Groundwater Analytical Results - Dissolved Metals, BRC Property
13. Summary of Groundwater Analytical Results - Total Metals, Former ILM Facility
14. Summary of Groundwater Analytical Results - Total Metals, BRC Property

Appendices

- A. Boring/Well Construction Logs
- B. Waste Disposal Documentation
- C. Hydrographs
- D. Groundwater Sampling Logs
- E. Analytical Reports/Chain-of-Custody Forms/Data Validation Reports
- F. Groundwater Data Tables
- G. TCE Time/Concentration Graphs